

Redmine - Defect #12342

TVHeadend doesn't detect dvb-T tuner part of Technotrend CI-3650 CT on Raspbmc on Raspberry Pi

2012-11-10 08:20 - Thomas Asaa

Status:	Closed	Start date:	
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Affected version:	
Resolution:	Invalid		
Description I have a problem with TVHeadend detecting the dvb-T part of my Technotrend CI-3650 CT tuner. In TVAdapters I only can select the dvb-C tuner, not the dvb-T tuner. I'm running Raspbmc on Raspberry Pi. I assumed it would work "out of the box", according to this link: http://www.linuxtv.org/wiki/index.php/TechnoTrend_TT-connect_CT-3650_CI So then I added lines as described here: http://www.mail-archive.com/linux-media@vger.kernel.org/msg43015.html The log file says both tuners are initialized, even without the CI card inserted. But TVHeadend detects only the dvb-C tuner. In Denmark dvb-T are decoded as MPEG4. What can be the problem? Please help anyone! NB:I'm a Linux novice, so please explain any suggestions in details... Kind regards Thomas			

History

#1 - 2012-11-10 10:54 - Jean-Philippe Lang

- Status changed from New to Closed
- Resolution set to Invalid

Wrong issue tracker. We track Redmine issues here.